

EPA Region 5 Records Ctr.



323464

Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave Di Traglia ^{PCN}


Location: LPC- 16312103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave Di Traglia ^{PCN}

Location: LPC- 16312103

St. Clair Co.

Sauget 1

Comments: Photograph taken

toward the



Date: October 2, 1981

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia PCm

Location: LPC- 16312103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the SSW



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia PCm

Location: LPC- 16312103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the North



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia^{PCM}

Location: LPC- 16312103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: _____

Time: 10/2/81 A.M. P.M.

Photograph By:

Dave DiTraglia^{PCM}

Location: LPC- 16312103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the north northeast



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia AM

Location: LPC- 163/2/03

St. Clair Co.

Sargeant 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia AM

Location: LPC- 163/2/03

St. Clair Co.

Sargeant 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia ^{pm}

Location: LPC- 16312103

St. Clair Co.

Sargeant / Toxic Dump

Comments: Photograph taken

toward the west southwest



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia ^{DCM}

Location: LPC- 16312103

St. Clair Co.

Sargeant / Toxic Dump

Comments: Photograph taken

toward the west southwest



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia ^{per}

Location: LPC- 16312103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the east



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia ^{per}

Location: LPC- 16312103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave Di Traglia PCm

Location: LPC- 163/2103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the ~~north~~ west

~~Southwest~~



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave Di Traglia PCm


Location: LPC- 163/2103

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia PCN


Location: LPC- 16312103

St. Clair Co.

Sargeat 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia PCN


Location: LPC- 16312103

St. Clair Co.

Sargeat 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia ^{PM}

Location: LPC- 16312103

St. Clair Co.

Sanget 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia ^{PM}

Location: LPC- 16312103

Sanget St. Clair Co.

Sanget 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave Di Traglia^{pcn}


Location: LPC- 163/2/03

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the east



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave Di Traglia^{pcn}

Location: LPC- 163/2/03

St. Clair Co.

Sauget 1 Toxic Dump

Comments: Photograph taken

toward the east



Date: 10/2/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia PCm


Location: LPC- 163/2103

St. Clair Co.

Sunset 1 Toxic Dump

Comments: Photograph taken

toward the east



Date: 10/20/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia PCm


Location: LPC- 163/2103

St. Clair Co.

Sunset 1 Toxic Dump

Comments: Photograph taken

toward the west



Date: 10/20/81

Time: _____ A.M. P.M.

Photograph By:

Dave DiTraglia ^{PCM}

Location: LPC- 16312103

St. Clair Co.

Target 1 Toxic Dump

Comments: Photograph taken

toward the southwest



Date: _____

Time: _____ A.M. P.M.

Photograph By:

Location: LPC-

_____ Co.

Comments: Photograph taken

toward the

Date: OCTOBER 2, 1981

Time: A.M. P.M.

Photograph By: DMB

Dave Ditraglia USEPA


Location: LPC- 16312103

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the WEST



Date: OCTOBER 2, 1981

Time: A.M. P.M.

Photograph By: DMB

Dave Ditraglia USEPA

Location: LPC- 16312103

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the NORTH



Date: OCTOBER 2, 1981

Time: _____ A.M. P.M.

Photograph By: DMB

DAVE ALTRAGLIA USEPA

Location: LPC- 16312103

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the SOUTH



Date: OCTOBER 2, 1981

Time: _____ A.M. P.M.

Photograph By: DMB

DAVE ALTRAGLIA USEPA


Location: LPC- 16312103

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the WEST



Date: OCTOBER 2, 1981

Time: A.M. P.M.

Photograph By: RM

Steve Litraglia USEPA

Location: LPC- 16312103

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the WEST

Date: OCTOBER 2, 1981

Time: A.M. P.M.

Photograph By: RM

Steve Litraglia USEPA


Location: LPC- 16312103

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the WEST



Date: OCTOBER 2, 1981

Time: _____ A.M. P.M.

Photograph By: MS

Dave Nitraglia USEPA

Location: LPC- 16 3121 03

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the NORTH



Date: OCTOBER 2, 1981

Time: _____ A.M. P.M.

Photograph By: MS

Dave Nitraglia USEPA


Location: LPC- 16 3121 03

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the WEST



Date: OCTOBER 2, 1981

Time: _____ A.M. P.M.

Photograph By: NTD

Dave Litraglia USEPA


Location: LPC- 16312103

ST. CLAIR Co.

SALGET 1 TOXIC

Comments: Photograph taken

toward the NORTH



Date: _____

Time: _____ A.M. P.M.

Photograph By: _____

Location: LPC-

_____ Co.

Comments: Photograph taken

toward the

Date: OCTOBER 2, 1981

Time: _____ A.M. P.M.

Photograph By: DM

Dave Mitraglia USEPA


Location: LPC- 16312103

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the EAST



Date: OCTOBER 2, 1981

Time: _____ A.M. P.M.

Photograph By: DM

Dave Mitraglia USEPA

Location: LPC- 16312103

ST. CLAIR Co.

SAUGET 1 TOXIC

Comments: Photograph taken

toward the NORTHWEST



Date: May 21, 1986

Time: 10:07 A.M. P.M.

Photograph By:

MMcCarthy


Location: LPC- 1631210001

St. Clair Co.

Sauget / Sauget

Comments: Photograph taken

toward the North



Date: May 21, 1986

Time: 10:08 A.M. P.M.

Photograph By:

MMcCarthy


Location: LPC- 1631210001

St. Clair Co.

Sauget / Sauget

Comments: Photograph taken

toward the North



RECEIVED

JUN 24 1986

IEPA-DLPC

1631210001

Date: May 21, 1986

Time: 10:27 A.M. P.M.

Photograph By:

J. McCauley

Location: LPC- 1631210001

St. Clair Co.

Sauget / Sauget

Comments: Photograph taken

toward the West



Date: May 21, 1986

Time: 10:45 A.M. P.M.

Photograph By:

J. McCauley

Location: LPC- 1631210001

St. Clair Co.

Sauget / Sauget

Comments: Photograph taken

toward the South



RECEIVED

JUN 24 1986

IEPA-DLPC

L/IEPA-DLPC